

Management Acceptance Quality System Manager Acceptance Guide

To qualify as a quality manager a person should have:

1. Practical experience and expertise in the application of aviation safety standards and safe operating practices.
2. Appropriate management experience in a comparable organization.
3. Five years relevant work experience of which at least two years should be from the aeronautical industry in an appropriate position.
4. Experience implementing and/or managing aviation quality system.
5. Experience in conducting safety/quality audits and inspections.
6. Computer literacy and superior analytical skills.
7. Have completed at least the following quality system training:
 - a. Quality management system.
 - b. Quality assurance program.
 - c. Audit techniques.
 - d. Human factor and crew resources management.
8. Comprehensive knowledge of:
 - a. JCAR OPS 1 and any associated requirements and procedures.
 - b. AOC operations specifications.
 - c. The need for, and content of, the relevant parts of the AOC holder's Operations Manual - Quality system manual & safety management system manual.